

# EG25-G-GB Release Notes

## LTE Standard Module Series

Rev. EG25-G-GB\_Firmware\_Release\_Notes\_V0708\_30.006.30.006

Date: 2022-01-17



Our aim is to provide customers with timely and comprehensive service. For any assistance, please contact our company headquarters:

**Quectel Wireless Solutions Co., Ltd.**

Building 5, Shanghai Business Park Phase III (Area B), No.1016 Tianlin Road, Minhang District, Shanghai 200233, China

Tel: +86 21 5108 6236

Email: [info@quectel.com](mailto:info@quectel.com)

**Or our local office. For more information, please visit:**

<http://www.quectel.com/support/sales.htm>.

**For technical support, or to report documentation errors, please visit:**

<http://www.quectel.com/support/technical.htm>

Or email to [support@quectel.com](mailto:support@quectel.com).

**Disclaimer**

While Quectel has made efforts to assure the accuracy of this document, unless otherwise provided by valid agreement, Quectel assumes no liability resulting from any inaccuracies or omissions in this document, or from use of the information obtained herein. Quectel reserves the right to make changes to any contents described herein and reserves the right to revise this document and to make changes from time to time in content hereof with no obligation to notify any person of revisions or changes. Before using any updated software, please read this statement carefully. By accessing or using the said software you irrevocably and unconditionally accept and confirm that you agree to be bound by this statement. In the event you disagree with any provision hereof and would not like to be bound by this statement you shall cease use of the said software immediately.

**Duty of Confidentiality**

The Receiving Party shall keep confidential all documentation and information provided by Quectel, except when the specific permission has been granted by Quectel. The Receiving Party shall not access or use Quectel's documentation and information for any purpose except as expressly provided herein. Furthermore, the Receiving Party shall not disclose any of the Quectel's documentation and information to any third party without the prior written consent by Quectel. For any noncompliance to the above requirements, unauthorized use, or other illegal or malicious use of the documentation and information, Quectel will reserve the right to take legal action.

**Copyright**

The information contained here is proprietary technical information of Quectel Wireless Solutions Co., Ltd. Transmitting, reproducing, disseminating and editing this document as well as using the content without permission are forbidden. Offenders will be held liable for payment of damages. All rights are reserved in the event of a patent grant or registration of a utility model or design.

***Copyright © Quectel Wireless Solutions Co., Ltd. 2022. All rights reserved.***

## 1. Preamble

This document provides the Release Notes for EG25-G-GB firmware version **EG25GGBR07A08M2G\_30.006.30.006**. It describes major changes compared to for EG25-G-GB firmware version **EG25GGBR07A08M2G\_30.005.30.005**.

## 2. Matters Needing Attention

| SN  | Brief Description  |
|-----|--|
| [1] | Multiple PDN is not supported by MBIM.                                   |
| [2] | In AP mode, due to memory limitations, WIFI supports 10 clients at most. |

## 3. New Features

| Item/Category | Brief Description  | Since                    |
|---------------|--|--------------------------|
| GENERAL       | Supported T-Mobile SIM card (311-882).   | R07A08_30.0<br>05.30.005 |
| GENERAL       | Supported ES8311 codec driver.   | R07A08_30.0<br>05.30.005 |
| NETWORK       | 1. Extended the <b>AT+QOPSCFG="displaybw"</b> command to control whether <b>AT+QOPS</b> displays the bandwidth under LTE.<br>2. Extended the <b>AT+QOPS</b> command to support displaying bandwidth under LTE. | R07A08_30.0<br>04.30.004 |
| TCP/UDP       | Added the AT command <b>AT+QCFG="TCP/SendMode"</b> to configure TCP sending mode.  | R07A08_30.0<br>04.30.004 |
| WIFI          | Added URC <b>+QWIFIAUTHFAIL</b> to report a device(STA) fails to connect to the module (configured as AP) for authorization failure.   | R07A08_30.0<br>04.30.004 |
| AUDIO         | Extended the AT command <b>AT+QCFG="tone/incoming"</b> to support playing the specified ringtone when a call came in.  | R07A08_30.0<br>03.30.003 |
| DFOTA         | Added AT command <b>AT+QFOTADL=&lt;url&gt;,"down_to_ufs",&lt;local_file_name&gt;[,&lt;usrn ame&gt;,&lt;password&gt;]</b> to download the FTP file to local UFS directory.                                      | R07A08_30.0<br>03.30.003 |
| MMS           | Added AT command <b>AT+QCFG="mms_rec_control"</b> to control whether to save the received MMS.   | R07A08_30.0<br>03.30.003 |
| MQTT          | Added AT command <b>AT+QMTCFG="protocol/check"</b> to configure  | R07A08_30.0              |

|                   |   |                          |
|-------------------|---|--------------------------|
|                   | whether to check MQTT header information.   | 03.30.003                |
| <b>NETWORK</b>    | Added AT command <b>AT+QCFG="cops_control"</b> to control <b>AT+COPS</b> to scan band, not affecting the band scan of <b>AT+QCFG="nwscanmodeex"</b> . | R07A08_30.0<br>03.30.003 |
| <b>QuecThing</b>  | Supported QuecThing.  | R07A08_30.0<br>03.30.003 |
| <b>SMS</b>        | Extended AT command <b>AT+QCFG="ltesms/format"</b> to send SMS in 3GPP2 format only and receive SMS in 3GPP2 and 3GPP format at the same time.        | R07A08_30.0<br>03.30.003 |
| <b>UAC</b>        | Supported 16K sampling rate by UAC.   | R07A08_30.0<br>03.30.003 |
| <b>Voice Call</b> | Added DSCI report in emergency call.  | R07A08_30.0<br>03.30.003 |
| <b>WIFI</b>       | Supported LTE and WIFI coexistence mechanism.   | R07A08_30.0<br>03.30.003 |
| <b>GENERAL</b>    | Supported Optus MBN.  | R07A08_30.0<br>03.30.003 |
| <b>GENERAL</b>    | Extended AT command <b>AT+QCFG="cmux/urcport"</b> to support turning off CMUX port to report URC.   | R07A08_30.0<br>03.30.003 |
| <b>GENERAL</b>    | Supported outputting \$PQXMI NMEA sentences, and not outputting \$PQXMI sentences by default.   | R07A08_30.0<br>03.30.003 |
| <b>GENERAL</b>    | Added <b>AT+QCFG="usbauto"</b> command to control USB network card to automatically adapt to Windows, Linux, macOS without a driver.                  | R07A08_30.0<br>03.30.003 |
| <b>GENERAL</b>    | Added AT command <b>AT+QFORMATUSRDATA</b> to format usrdata ubi.  | R07A08_30.0<br>03.30.003 |
| <b>GENERAL</b>    | Added AT command <b>AT+QCFG="secbootstat"</b> to get whether the secboot is enabled.  | R07A08_30.0<br>03.30.003 |
| <b>GENERAL</b>    | Added AT command <b>AT+QGPPSPAI</b> to obtain GNSS positioning assistance information.  | R07A08_30.0<br>03.30.003 |
| <b>GENERAL</b>    | Supported Hong Kong Telecom SIM card, with ICCID 8985231 and PLMN 45431.  | R07A08_30.0<br>03.30.003 |
| <b>GENERAL</b>    | Supported STC MBN.  | R07A08_30.0<br>03.30.003 |
| <b>GENERAL</b>    | Added <b>AT+QCFG="enable_GEA1"</b> to enable GPRS Encryption algorithm GEA/1.   | R07A08_30.0<br>03.30.003 |
| <b>GENERAL</b>    | Supported Rogers MBN.   | R07A08_30.0<br>03.30.003 |
| <b>GENERAL</b>    | Added <b>AT+QCFG="lanip"</b> to modify the range of LAN IP.   | R07A08_30.0<br>03.30.003 |
| <b>GENERAL</b>    | Supported LGU MBN.  | R07A08_01.0<br>03.01.003 |

|                 |  |                          |
|-----------------|--|--------------------------|
| GENERAL         | Supported RPM configuration for DT MBN.  | R07A08_01.0<br>03.01.003 |
| GENERAL         | Added <b>AT+QGSN</b> to get module GSN number and <b>AT+QIMI</b> to get IMEI number.               | R07A08_01.0<br>03.01.003 |
| DTMF            | Added AT command <b>AT+QWDTMF</b> to play DTMF files or send it to Far-end.                        | R07A08_01.0<br>03.01.003 |
| GENERAL         | Supported SKT MBN with version 202007071。  | R07A08_01.0<br>03.01.003 |
| GENERAL         | Optimized Telstra MBN related configuration.   | R07A08_01.0<br>03.01.003 |
| QuecLocator2.0  | Added AT command <b>AT+QLBSCFG="contextid"</b> to configure the QuecLocator context ID.            | R07A08_01.0<br>03.01.003 |
| GENERAL         | Supported USCC MBN.  | R07A08_01.0<br>03.01.003 |
| DFOTA           | Added HTTP DFOTA to parse URL with type of http://user:password@www.baidu.com.                     | R07A08_01.0<br>02.01.002 |
| GENERAL         | Added AT command <b>AT+QCFG="fast/poweroff"</b> to enable/disable fast power off function.         | R07A08_01.0<br>02.01.002 |
| NETWORK         | Added AT command <b>AT+QCFG="qoos"</b> to optimize network search power consumption in sleep mode. | R07A08_01.0<br>02.01.002 |
| SMS             | Added <b>AT+QCFG="sms_control"</b> to control SMS sending and reception.                           | R07A08_01.0<br>02.01.002 |
| Voice Call      | Added <b>AT+QCFG="call_control"</b> command to control voice MO and MT functions.                  | R07A08_01.0<br>02.01.002 |
| TCP SSL         | Added AT command <b>AT+QSSLRECV</b> to read the remaining data.                                    | R07A08_01.0<br>02.01.002 |
| GENERAL         | Supported to report URC to MCU when thermal mitigate level was up to 3.                            | R07A08_01.0<br>02.01.002 |
| NETWORK         | Added AT command <b>AT+QEGPAPN</b> to query the actual APN and the configured APN.                 | R07A08_01.0<br>02.01.002 |
| QuecLocator 2.0 | Added AT command <b>AT+QLBSEX</b> to enter the cell parameter for positioning.                     | R07A08_01.0<br>02.01.002 |
| MBIM            | Added MBIM function.   | R07A08_01.0<br>02.01.002 |
| NETWORK         | Added the function of preferential registration to the network for the specified LTE band.         | R07A08_01.0<br>02.01.002 |
| GENERAL         | Imported domestic operators.   | R07A08_01.0<br>02.01.002 |
| NETWORK         | Added jamming detection function.  | R07A08_01.0<br>02.01.002 |
| Voice Call      | Added AT command <b>AT+QCFG="voice_busytone"</b> to enable/disable busytone playback.              | R07A08_01.0<br>02.01.002 |
| GENERAL         | Added class 6 APN for Verizon.   | R07A08_01.0              |

|                |  |                          |
|----------------|--|--------------------------|
|                |  | 02.01.002                |
| TCP SSL        | Added AT command <b>AT+QSSLCFG="alpn"</b> to set SSL alpn.   | R07A08_01.0<br>02.01.002 |
| GENERAL        | Added AT command <b>AT+QCFG="wakepin/level"</b> Set the wake-up pin level and whether to enable the wake-up function.  | R07A08_01.0<br>02.01.002 |
| TCP SSL        | Added <b>AT+QSSLCFG="session_cache"</b> command to optimize TCP SSL connection.  | R07A08_01.0<br>02.01.002 |
| AUDIO          | Supported recording and playing audio in AMR format.   | R07A08_01.0<br>02.01.002 |
| GENERAL        | Added AT command <b>AT+QOPS</b> to scan band.  | R07A08_01.0<br>02.01.002 |
| SIMCARD        | Added AT command <b>AT+QSIMCHK</b> to send UIM_AUTHENTICATE_REQ (UIM authentication).  | R07A08_01.0<br>02.01.002 |
| SIMCARD        | Added AT commands <b>AT+QSIMWRFREQ</b> to record the frequency of EF files written to SIM card and <b>AT+QSIMVOL</b> to configure SIM card supply voltage.                         | R07A08_01.0<br>02.01.002 |
| NETWORK        | Added AT commands <b>AT+QOPSCFG="scancontrol"</b> to configure bands to be scanned under 2G/3G/4G and <b>AT+QOPSCFG="displayrssi"</b> to enable/disable to display RSSI under LTE. | R07A08_01.0<br>02.01.002 |
| FILE           | Added File SFS function.   | R07A08_01.0<br>02.01.002 |
| TCP/UDP        | Added AT command <b>AT+QICFG="tcp/keepalive"</b> to configure whether to enable TCP keepalive function.  | R07A08_01.0<br>02.01.002 |
| GENERAL        | Added Bluetooth function (SPP, BLE, HFG) and AT command <b>AT+QCFG="spi/set"</b> to write a mark in rawdata to control the initialization of SPI6/UART6.                           | R07A08_01.0<br>02.01.002 |
| WIFI           | Added AT command <b>AT+QWIFICFG="bridgemode"</b> to support WIFI dongle function.  | R07A08_01.0<br>02.01.002 |
| WIFI           | Added <b>AT+QWIFICFG="dongle_mac"</b> to get the MAC address connecting to the ECM/RNDIS device.   | R07A08_01.0<br>02.01.002 |
| GENERAL        | Supported using <b>AT+CSCS</b> command with no SIM card inserted.  | R07A08_01.0<br>02.01.002 |
| QuecLocator2.0 | Added AT command <b>AT+QLBSCFG="latOrder"</b> .  | R07A08_01.0<br>01.01.001 |
| GENERAL        | Added AT command <b>AT+QMBNCFG="list"</b> .  | R07A08_01.0<br>01.01.001 |
| TCP/UDP        | Added AT command <b>AT+QCFG="tcp/windowsize"</b> .   | R07A08_01.0<br>01.01.001 |
| PPP            | Added AT command <b>AT+QCFG="ppp/sleep_ri"</b> .   | R07A08_01.0<br>01.01.001 |
| GENERAL        | Added AT command <b>AT+QCFG="iprulectl"</b> .  | R07A08_01.0<br>01.01.001 |
| GENERAL        | Added TF_Spain_VoLTE and TF_Germany_VoLTE MBN.   | R07A08_01.0<br>01.01.001 |

|            |  |                          |
|------------|--|--------------------------|
| NETWORK    | Added AT command <b>AT+QGPAPN</b> .  | R07A08_01.0<br>01.01.001 |
| WIFI       | Added AT command <b>AT+QWIFICFG="version"</b> .  | R07A08_01.0<br>01.01.001 |
| NETWORK    | Added AT command <b>AT+QRRCCONSTATE</b> .  | R07A08_01.0<br>01.01.001 |
| NETWORK    | Added AT command <b>AT+QICSGPEH</b> .  | R07A08_01.0<br>01.01.001 |
| GENERAL    | Supported to report all URC via command <b>AT+QURCCFG="urcport","all"</b> .  | R07A08_01.0<br>01.01.001 |
| DTMF       | Added AT command <b>AT+QVTS</b> .  | R07A08_01.0<br>01.01.001 |
| PPP        | Added AT command <b>AT+QCFG="ppp/v4v6"</b> .   | R07A08_01.0<br>01.01.001 |
| NETWORK    | Added AT command <b>AT+QDISABLERETRY</b> .   | R07A08_01.0<br>01.01.001 |
| TCP SSL    | Added command of <b>AT+QSSSEND=0,0</b> to query the cache status of the <b>AT+QSSSEND</b> .  | R07A07_01.0<br>02.01.002 |
| GENERAL    | Added AT command <b>AT+QCFG="bip/auth"</b> .   | R07A07_01.0<br>02.01.002 |
| GENERAL    | Supported socket data forward and added related AT commands:<br><b>AT+QFWDCLIENT</b> ,<br><b>AT+QFWDSEVER</b> ,<br><b>AT+QFWDCLOSE</b> ,<br><b>AT+QFWDSEND</b> ,<br><b>AT+QFWDRECV</b> . | R07A07_01.0<br>02.01.002 |
| AUDIO      | Added UAC function.  | R07A07_01.0<br>02.01.002 |
| GENERAL    | Added TUNER function.  | R07A07_01.0<br>02.01.002 |
| GENERAL    | Added Commercial-DT MBN.   | R07A07_01.0<br>02.01.002 |
| NETWORK    | Added AT command <b>AT+QCFG="fast_dormancy"</b> .  | R07A07_01.0<br>02.01.002 |
| GENERAL    | Added AT command <b>AT+CCHO</b> , <b>AT+CCHC</b> and <b>AT+CGLA</b> .  | R07A07_01.0<br>02.01.002 |
| GENERAL    | Added URC for fumo pkg checking.   | R07A07_01.0<br>02.01.002 |
| HTTP       | Added the following AT commands:<br><b>AT+QHTTSEND</b> , <b>AT+QHHTPCFGEX</b> , <b>AT+QHHTTTPUT</b> and<br><b>AT+QHHTTTPUTFILE</b> .   | R07A07_01.0<br>02.01.002 |
| GENERAL    | Added Reliance MBN.  | R07A07_01.0<br>02.01.002 |
| Voice Call | Added AT commands<br><b>AT+QIMSACT</b> ,<br><b>AT+QDIAL</b> ,  | R07A07_01.0<br>01.01.001 |



| AT+QCHLDIPMPTY. |   |                          |
|-----------------|---|--------------------------|
| Voice Call      | Added AT command <b>AT+QECBM</b> only for Verizon.    | R07A07_01.0<br>01.01.001 |
| AUDIO           | Added AT command <b>AT+QAUDCFG="nau8810/config"</b> . | R07A05_01.0<br>01.01.001 |
| AUDIO           | Optimized AT command <b>AT+QAUDCFG="encgain"</b> .    | R07A04_01.0<br>01.01.001 |

## 4. Improved Features

| Item/Category | Brief Description   | Since                    |
|---------------|---|--------------------------|
| DFOTA         | Solved the problem that error code 502 was reported during DFOTA upgrade.   | R07A08_30.0<br>06.30.006 |
| TCP SSL       | Solved the problem of no RI pin pulling when data reported in SSL client transparent transmission mode.   | R07A08_30.0<br>06.30.006 |
| WIFI          | Updated WIFI firmware.  | R07A08_30.0<br>06.30.006 |
| GENERAL       | Optimized the dual serial port function to solve the problem of abnormal serial communication when AT commands is used for large data transmission. | R07A08_30.0<br>06.30.006 |
| GENERAL       | Solved the problem of CVE-2021-31698.   | R07A08_30.0<br>06.30.006 |
| GENERAL       | Set voice centric for Verizon MBN.  | R07A08_30.0<br>06.30.006 |
| GENERAL       | Modified the attach APN to telstra.internet for Telstra operator.   | R07A08_30.0<br>06.30.006 |
| GENERAL       | Set the ROW MBN profile1 to null and profile3 APN name to sos apn name.   | R07A08_30.0<br>06.30.006 |
| DFOTA         | Solved the problem of error code 701 returned in URC after DFOTA HTTPS download failure.  | R07A08_30.0<br>05.30.005 |
| GENERAL       | Fixed CVE-2021-31698.   | R07A08_30.0<br>05.30.005 |
| GENERAL       | Integrated Verizon SUPL Certificates in Verizon MBN.  | R07A08_30.0<br>05.30.005 |
| GENERAL       | Removed the configuration of default MTU 1430 in DCM MBN.   | R07A08_30.0<br>05.30.005 |
| GENERAL       | Solved the problem that AT commands may be blocked due to powering on and off the module repeatedly.  | R07A08_30.0<br>04.30.004 |
| GENERAL       | Solved the problem that <b>AT+QDAI</b> failed to set long and short frames.   | R07A08_30.0<br>04.30.004 |



|                   |  |                          |
|-------------------|--|--------------------------|
| <b>GENERAL</b>    | Solved the problem that <b>AT+QCFG="qcautoconnect"</b> could not enable the automatic connection in ECM or RNDIS mode.   | R07A08_30.0<br>04.30.004 |
| <b>GENERAL</b>    | Solved the problem that after switching <b>AT+CFUN=0</b> and <b>AT+CFUN=1</b> , the APN type of "atm2mglobal" was changed from IPV4V6 to IPV4 after ATT was activated and the module registered to the network successfully. | R07A08_30.0<br>04.30.004 |
| <b>AUDIO</b>      | Solved the problem that the following commands returned ERROR and CME ERROR at the same time:<br>1. <b>AT+QAUDRD</b><br>2. <b>AT+QAUDPLAY</b><br>3. <b>AT+QPSND</b><br>4. <b>AT+QWTTTS</b><br>5. <b>AT+QLDTMF</b>            | R07A08_30.0<br>03.30.003 |
| <b>AUDIO</b>      | Solved the problem that the ACDB file imported by <b>AT+QACDBLOAD</b> could not take effect.   | R07A08_30.0<br>03.30.003 |
| <b>AUDIO</b>      | Solved the problem the audio recording could not work normally after <b>AT+QMIC</b> set gain of MIC.   | R07A08_30.0<br>03.30.003 |
| <b>DFOTA</b>      | Supported using the fixed baud rate set before the upgrade during DFOTA upgrade.   | R07A08_30.0<br>03.30.003 |
| <b>DFOTA</b>      | Solved the problem that the module could not report the DFOTA upgrade result to the Verizon server after the OMA-DM DFOTA upgrade ended.   | R07A08_30.0<br>03.30.003 |
| <b>FTP</b>        | Solved the problem of timeout error (error code 609 returned) when executing <b>AT+QFTPOPEN</b> to log in to the FTP(S) server.  | R07A08_30.0<br>03.30.003 |
| <b>HTTP</b>       | Solved the problem that the module automatically rebooted when <b>AT+QHTTPPOSTFILE</b> sends a POST request to HTTP(S) server through a file larger than 1M.   | R07A08_30.0<br>03.30.003 |
| <b>MQTT</b>       | Solved the problem that the MQTT disconnected when receiving the message with QoS level 2 subscribed successfully.   | R07A08_30.0<br>03.30.003 |
| <b>MQTT</b>       | Solved the problem that when <b>AT+QIDEACT</b> was executed immediately after <b>AT+QMTOPEN</b> execution for the first time, +QMTSTAT: 0,2 was reported continuously after <b>AT+QMTOPEN</b> execution again.               | R07A08_30.0<br>03.30.003 |
| <b>MQTT</b>       | Solved the problem of failure to connect to some servers caused by the inability to enable MQTT SN1.   | R07A08_30.0<br>03.30.003 |
| <b>NETWORK</b>    | Change the range of SINR value returned by <b>AT+QENG="SERVINGCELL"</b> from (0~250) to (-20~30).  | R07A08_30.0<br>03.30.003 |
| <b>PPP</b>        | Solved the problem that AT port may not work normally after executing <b>AT+CGACT=1,1</b> to activate the first PDP context which has been activated by default again.   | R07A08_30.0<br>03.30.003 |
| <b>Voice Call</b> | Solved the problem that there may be no busy tone displayed when the call was hung up after enabling busy tone playing via <b>AT+QCFG="voice_busytone"</b> .   | R07A08_30.0<br>03.30.003 |

|         |   |                          |
|---------|---|--------------------------|
| WIFI    | Solved the problem that without SIM card, ECM could not work normally while FC20 was in the WIFI STA mode.  | R07A08_30.0<br>03.30.003 |
| WIFI    | Solved the problem that after setting <b>AT+QWSSIDHEX=1</b> , rebooting the module, 0 was always returned by <b>AT+QWSSIDHEX?</b> .                         | R07A08_30.0<br>03.30.003 |
| WIFI    | Solved the problem that WIFI could not work normally after WIFI SSID was set via <b>AT+QWIFICFG="ssid"</b> .  | R07A08_30.0<br>03.30.003 |
| WIFI    | Solved the problem that IPv6 information could not be returned by <b>AT+QWIFICFG="stainfo"</b> .  | R07A08_30.0<br>03.30.003 |
| GENERAL | Updated LGU MBN version to 202103101.   | R07A08_30.0<br>03.30.003 |
| GENERAL | Fixed the problem that Telus VoLTE could not make VoLTE Call.   | R07A08_30.0<br>03.30.003 |
| GENERAL | Changed the MCFG_version version of USCC MBN from 0x05040D2 to 0x0504FC40.  | R07A08_30.0<br>03.30.003 |
| GENERAL | Solved the problem that ACDB files could not be obtained by <b>AT+QACDBLOAD?</b> .  | R07A08_30.0<br>03.30.003 |
| GENERAL | Changed KDDI configurations below:<br>The first APN to au.au-net.ne.jp, user name to user@au.au-net.ne.jp, password to au, and authentication type to CHAP. | R07A08_30.0<br>03.30.003 |
| GENERAL | For TMO, modified the voipMinSessionExpires to 90.  | R07A08_30.0<br>03.30.003 |
| GENERAL | Solved the problem that the usrdata ubi may be mounted abnormally in a short time after the module was powered off by executing <b>AT+QPOWD=0</b> .         | R07A08_30.0<br>03.30.003 |
| GENERAL | Optimized the jamming detection algorithm to improve the accuracy.  | R07A08_30.0<br>03.30.003 |
| GENERAL | Solved the problem that Host could not obtain the IP from MBIM if the network only allocated IP without DNS address.  | R07A08_30.0<br>03.30.003 |
| GENERAL | Updated SE13 TABLE date to 2020/12/21.  | R07A08_30.0<br>03.30.003 |
| GENERAL | Solved the problem that the module could not work normally when executing <b>AT+QGPGNMEA="GSV"</b> after searching for multiple satellites.                 | R07A08_30.0<br>03.30.003 |
| GENERAL | Solved the problem that <b>AT+QCFG="PCMCLK",0</b> could not turn off PCM clock.   | R07A08_30.0<br>03.30.003 |
| GENERAL | Updated the ATT MBN version to 202102031 to use the MTU size allocated by the network and change ue_usage_setting to DATA Centric.                          | R07A08_30.0<br>03.30.003 |
| GENERAL | Modified the third and fourth APN profile for SKT and updated SKT MBN version to 202103121.   | R07A08_30.0<br>03.30.003 |
| GENERAL | Updated DCM MBN version to 202104121 to solve the problem of unable to connect to TCP for data transmission after a successful                              | R07A08_30.0<br>03.30.003 |

|                |   |                          |
|----------------|---|--------------------------|
|                | network search.   |                          |
| <b>GENERAL</b> | When peer IP address length was more than 50 chars, silently truncated the string to 50 chars.  | R07A08_30.0<br>03.30.003 |
| <b>GENERAL</b> | Not triggered card power-down if EF-DIR read fails.   | R07A08_30.0<br>03.30.003 |
| <b>GENERAL</b> | Populated file attributes for EST file when card did not return FCP data.   | R07A08_30.0<br>03.30.003 |
| <b>GENERAL</b> | No sim E911 call for specific operators should not be blocked.  | R07A08_30.0<br>03.30.003 |
| <b>GENERAL</b> | Solved the problem that the Verizon OMA server could not be connected using IPv6.   | R07A08_30.0<br>03.30.003 |
| <b>GENERAL</b> | Modified the first APN to IPV6 only for TMO.  | R07A08_30.0<br>03.30.003 |
| <b>GENERAL</b> | Solved the problem that the uploaded ATT APN name of Object 11 instance 0 is null.  | R07A08_30.0<br>03.30.003 |
| <b>GENERAL</b> | Solved the problem URC broadcast could not work normally after enabling CMUX feature.   | R07A08_30.0<br>03.30.003 |
| <b>GENERAL</b> | Set the default MTU to 1430 for ATT.  | R07A08_30.0<br>03.30.003 |
| <b>GENERAL</b> | Updated Telstra MBN version to 202105192.   | R07A08_30.0<br>03.30.003 |
| <b>GENERAL</b> | Modified the configuration of the 2nd profile (IMS) for TMO to change the OVRIDEHOPDP to IPV6.  | R07A08_30.0<br>03.30.003 |
| <b>GENERAL</b> | Not to send UPDATE messages to the server immediately after the module was booted and registered to LwM2M successfully.               | R07A08_30.0<br>03.30.003 |
| <b>GENERAL</b> | Fixed the problem of incorrect RTC time synchronized from NITZ in some time zones.  | R07A08_30.0<br>03.30.003 |
| <b>GENERAL</b> | Optimized the operator's 3G Sunset solution to solve the problem of no network in some scenarios (such as roaming) at AT&T 3G Sunset. | R07A08_30.0<br>03.30.003 |
| <b>GENERAL</b> | Modified 2nd, 3rd, and 4th APN for KT MBN, and updated the KT MBN version to 202106221.   | R07A08_30.0<br>03.30.003 |
| <b>GENERAL</b> | Disabled fast dormancy feature for TMO.   | R07A08_30.0<br>03.30.003 |
| <b>GENERAL</b> | Updated ROW MBN version number to 202108022.  | R07A08_30.0<br>03.30.003 |
| <b>GENERAL</b> | Limited LTE band to B4&B13 for Verizon.   | R07A08_30.0<br>03.30.003 |
| <b>GENERAL</b> | Fixed the problem that the USB could not work normally when the module rebooted for the first time after DFOTA upgrade.               | R07A08_01.0<br>03.01.003 |
| <b>AUDIO</b>   | Optimized <b>AT+QLTONE</b> to play tone.  | R07A08_01.0<br>03.01.003 |

|            |  |                          |
|------------|--|--------------------------|
| GENERAL    | For non-Chinese operators, turned on the AGPS function.  | R07A08_01.0<br>03.01.003 |
| GENERAL    | Solved the problem that pcmclk could not be enabled by <b>AT+QCFG="PCMCLK"</b> .   | R07A08_01.0<br>03.01.003 |
| GENERAL    | Modified RF parameters to update the CEFS version to "EG25_G", 00011, 202006301.   | R07A08_01.0<br>03.01.003 |
| DTMF       | Extended <b>AT+QTONEDT=1</b> to support soft decode feature.   | R07A08_01.0<br>03.01.003 |
| TCP/UDP    | Increased the length of domain name returned by <b>AT+QSSLOPEN</b> from 40 bytes to 256 bytes.   | R07A08_01.0<br>03.01.003 |
| GENERAL    | Updated Telstra MBN version to 202007141.  | R07A08_01.0<br>03.01.003 |
| GENERAL    | Solved the problem that data sent and received by the module would lost after the module connected to the DTLS server.   | R07A08_01.0<br>03.01.003 |
| GENERAL    | Updated KT MBN version to 202007211.   | R07A08_01.0<br>03.01.003 |
| GENERAL    | Solved the problem that the incorrect value (0, indicating that RNDIS is not automatically connected) returned by <b>AT+QCFG="QCAUTOCONNECT"</b> after RNDIS mode was set by <b>AT+QCFG="usbnet",3</b> . | R07A08_01.0<br>03.01.003 |
| TCP SSL    | Solved the problem that memory leak occurred when unilateral and mutual authentication connection with SSL was performed.  | R07A08_01.0<br>03.01.003 |
| DFOTA      | Solved the problem that DFOTA upgrade failed when special characters included in the HTTP URL.   | R07A08_01.0<br>03.01.003 |
| GENERAL    | Fixed the problem that <b>AT+QWSSIDHEX</b> could not set SSID encoding mode to default text mode.  | R07A08_01.0<br>03.01.003 |
| TCP/UDP    | Extended <b>AT+QICFG="window/scale"</b> to configure TCP Window scale.   | R07A08_01.0<br>03.01.003 |
| GENERAL    | Solved the problem that the default values of HSDPA returned by <b>AT+QCFG="hsdpacat"</b> and HSUPA returned by <b>AT+QCFG="hsupacat"</b> were incorrect.  | R07A08_01.0<br>03.01.003 |
| Voice Call | Fixed the problem that <b>AT+CPBR</b> could not read emergency calls from SIM card.  | R07A08_01.0<br>03.01.003 |
| SMS        | Solved the problem that <b>AT+QCFG="urcport/sms"</b> could not set SMS reporting port to debug port.   | R07A08_01.0<br>03.01.003 |
| WIFI       | Solved the problem that WIF could not connect to the hidden SSID.  | R07A08_01.0<br>03.01.003 |
| TCP/UDP    | Solved the problem that the number of actually connected clients did not match the set clients when the module was used as a TCP server.   | R07A08_01.0<br>03.01.003 |
| GENERAL    | Solved the problem that after QBI service closed, MBIM could not work normally when it was repeatedly opened or closed.  | R07A08_01.0<br>03.01.003 |
| SMS        | Solved the problem that the AT port could not work normally due to the execution of the <b>AT+QCFG="sms/listmsgmap"</b> command.   | R07A08_01.0<br>03.01.003 |
| FTP        | Solved the problem that error code 627 returned when data was downloaded discontinuously through FTP.  | R07A08_01.0<br>03.01.003 |

|         |  |                          |
|---------|--|--------------------------|
| MQTT    | Corrected the response format of <b>AT+QMTUNS=?</b> from +QMTSUB to +QMTUNS.   | R07A08_01.0<br>03.01.003 |
| FTP     | Solved the problem that error code 619 may be returned when PUT file via FTP.  | R07A08_01.0<br>03.01.003 |
| FILE    | Solved the problem that the module may not work when uploading 10K files to the SFS via <b>AT+QFUPL="SFS:10K.txt",10240</b> .  | R07A08_01.0<br>03.01.003 |
| HTTP    | Solved the problem that after connecting HTTP(S) server successfully with wrong URL and sending GET request through <b>AT+QHTTPGET</b> , executing <b>AT+QHTTPSTOP</b> to cancel HTTP(S) request before URC reported, AT port may not work normally. | R07A08_01.0<br>03.01.003 |
| HTTP    | Solved the problem that an extra +QHTTPURC: "closed" reported when enabling HTTP(S) session closing reporting through <b>AT+QHTTPCFG="closed/ind"</b> .  | R07A08_01.0<br>03.01.003 |
| HTTP    | Solved the problem that <b>AT+QHTTPGET</b> may not send the GET request to HTTP(S) server and there may be no timeout occurred.  | R07A08_01.0<br>03.01.003 |
| GENERAL | Fixed the deadlock occurred when loading/unloading Mac driver.   | R07A08_01.0<br>03.01.003 |
| GENERAL | Updated goldenbin to QL_FC20_V05 for customer requirement.   | R07A08_01.0<br>03.01.003 |
| TCP/UDP | Solved the problem that after connecting to TCP server through <b>AT+QIOPEN</b> for 60 seconds, the module did not send TCP disconnection wave after <b>AT+QICLOSE</b> was executed.   | R07A08_01.0<br>03.01.003 |
| GENERAL | Disabled VICE feature for Verizon.   | R07A08_01.0<br>03.01.003 |
| GENERAL | Modified the value of voipMinSessionExpires to 90 for Commercial-TMO_VoLTE MBN.  | R07A08_01.0<br>03.01.003 |
| BT      | Solved the problem that some device information could not include in the scan result returned by <b>AT+QBTSCAN</b> .   | R07A08_01.0<br>03.01.003 |
| HTTP    | Solved the problem of an error code 702 reported when there was no response from TCP server after HTTP PUT request was sent.   | R07A08_01.0<br>03.01.003 |
| WIFI    | Solved the problems below:<br>1. OK was unexpectedly returned when the password length configured by <b>AT+QWIFICFG="auth"</b> is out of range (greater than 63 bytes).<br>2. The return value of <b>AT+QWIFICFG="auth"</b> was incorrect.           | R07A08_01.0<br>03.01.003 |
| TCP SSL | Solved the problem that there was one more empty line on the "cacertex" certificate path returned by <b>AT+QSSLCFG="cacertex"</b> .  | R07A08_01.0<br>03.01.003 |
| SMS     | Optimized SMS feature to solve the problem that after the SMS is received, the abnormal URC +CMTI: ,0 was reported, and no content has been read.  | R07A08_01.0<br>03.01.003 |
| GENERAL | Solved the problem that special character 7bit 0x00f1 could not be displayed.  | R07A08_01.0<br>02.01.002 |
| GENERAL | Updated mmgsdi_se13_table.h.   | R07A08_01.0<br>02.01.002 |
| HTTP    | Optimized the feature of HTTP after enabling rspout/auto.  | R07A08_01.0<br>02.01.002 |
| GENERAL | Optimized AT command of <b>AT+QCFG="DIVCTL"</b> to solve the problem of incorrect length of  | R07A08_01.0<br>02.01.002 |



|                 |  |                          |
|-----------------|--|--------------------------|
|                 | "/nv/item_files/modem/lte/ML1/rx_tuning_chan".   |                          |
| GENERAL         | Solved the problem of error occurred when executing <b>AT+QFWDCLIENT=1,3,"IP","TCP","220.180.239.212",8007</b> without dialing.  | R07A08_01.0<br>02.01.002 |
| GENERAL         | Optimized <b>AT+QGPSCFG="outport","uartdebug"</b> to solve the problem that the GPS URC could not output from debug port.  | R07A08_01.0<br>02.01.002 |
| GENERAL         | Optimized <b>AT+QWWAN</b> command to solve the problem of file storage path error.   | R07A08_01.0<br>02.01.002 |
| GENERAL         | Update Telecom MBN version number to 202001161.  | R07A08_01.0<br>02.01.002 |
| GENERAL         | Solved the problem that WCDMA Band 4 and Band 8 diversity were opened unexpectedly by <b>AT+QCFG="diversity",1</b> .   | R07A08_01.0<br>02.01.002 |
| GENERAL         | Optimized the history call record function.  | R07A08_01.0<br>02.01.002 |
| SIMCARD         | Enabled FEATURE_MMGSDI_IGNORE_INIT_ERRO configuration to identify invalid SIM card.  | R07A08_01.0<br>02.01.002 |
| MQTT            | Solved the problem that after setting willmessage with a length of 256 bytes through <b>AT+QMTCFG="WILLEX"</b> , willtopic will also be returned after willmessage in URC.             | R07A08_01.0<br>02.01.002 |
| WIFI            | Solved the problem of failed to enable WIFI after configuring WIFI dual AP (AP0 + AP1) mode.   | R07A08_01.0<br>02.01.002 |
| SMS             | Solved the problem that the current operator's SMS center number could not be displayed after enabling the SIM card hot-plugging function.   | R07A08_01.0<br>02.01.002 |
| Queclocator 2.0 | Modified parameter format for AT commands related to base station positioning locator/LBS 2.0 as <b>AT+QLBSCFG?</b> , <b>AT+QLBSCFG=?</b> and <b>AT+QLBSCFG="token"</b> .              | R07A08_01.0<br>02.01.002 |
| Queclocator 2.0 | Solved the problem that the error code returned incorrectly after executing <b>AT+QLBS</b> .   | R07A08_01.0<br>02.01.002 |
| NETWORK         | Optimized <b>AT+QRRCCONSTATE</b> command.  | R07A08_01.0<br>02.01.002 |
| FTP             | Optimized FTP upload and download processes.   | R07A08_01.0<br>02.01.002 |
| NETWORK         | Optimized <b>AT+QCFG="fast_dormancy"</b> to support fast dormancy mode 3.  | R07A08_01.0<br>02.01.002 |
| NETWORK         | Optimized AT command <b>AT+QCFG="lte/preferfre"</b> to solve the problem of incorrect value of bandwidth parameter.  | R07A08_01.0<br>02.01.002 |
| MQTT            | Optimized AT command <b>AT+QMTPUBEX</b> to solve the problem of unstable module caused by the server disconnecting actively after entering data mode and Water Mark has been released. | R07A08_01.0<br>02.01.002 |
| Voice Call      | Optimized the three-party call function.   | R07A08_01.0<br>02.01.002 |
| FTP             | Supported multiple server response parsing in FTP mode.  | R07A08_01.0<br>02.01.002 |
| GENERAL         | Solved the problem that the computer could not connect to the network after executing <b>AT+QWWAN=1</b> .  | R07A08_01.0<br>02.01.002 |

|                   |  |                          |
|-------------------|--|--------------------------|
| <b>NETWORK</b>    | Optimized Telecom LTE ONLY IoT card network registration.  | R07A08_01.0<br>02.01.002 |
| <b>Voice Call</b> | Reported DSCI when making an emergency call.   | R07A08_01.0<br>02.01.002 |
| <b>GENERAL</b>    | Solved the problem of reporting error code 707 (HTTP (S) network open failed) when using <b>AT+QLBS</b> for positioning under AUTO or fixed 4G mobile network. | R07A08_01.0<br>02.01.002 |
| <b>GENERAL</b>    | Update ROW MBN version to 201905141.   | R07A08_01.0<br>02.01.002 |
| <b>GENERAL</b>    | Update the ID of Profile5 in VERIZON MBN.  | R07A08_01.0<br>02.01.002 |
| <b>NETWORK</b>    | Solved that problem of unable to re-initialize Home PLMN search when 313-100 SIM was registered on a 310-410 PLMN.   | R07A08_01.0<br>02.01.002 |
| <b>GENERAL</b>    | Optimized <b>AT+QCFG="DISRPLMN"</b> command to support disabling RPLMN and RPLMNACT.   | R07A08_01.0<br>02.01.002 |
| <b>GENERAL</b>    | Extended <b>AT+QFOTADL</b> command to increase DFOTA upgrade path length.  | R07A08_01.0<br>02.01.002 |
| <b>MMS</b>        | Solve the problem that MMS proxy addresses starting with 0 could be set with <b>AT+QMMSCFG="proxy"</b> .   | R07A08_01.0<br>02.01.002 |
| <b>FTP</b>        | Solved the problem that the module could not work normally after executing <b>AT+CFUN=0</b> on other AT ports during FTP upload or download.                   | R07A08_01.0<br>02.01.002 |
| <b>GENERAL</b>    | Updated reliance MBN version to 202003251.   | R07A08_01.0<br>02.01.002 |
| <b>TCP/UDP</b>    | Solved the problem that after activating PDP, the AT port may not work normally after executing <b>AT+QIDEACT</b> command immediately without response.        | R07A08_01.0<br>02.01.002 |
| <b>GENERAL</b>    | Solved the problem of error returned when querying NV553 after activating ATT MBN.   | R07A08_01.0<br>02.01.002 |
| <b>GENERAL</b>    | Solved the problem that the default server port (80) could not be obtained by <b>AT+QLBSCFG?</b> .   | R07A08_01.0<br>02.01.002 |
| <b>GENERAL</b>    | Solved the problem that the SMS reporting port could not be set as the debug port by <b>AT+QCFG="urcport/sms"</b> .  | R07A08_01.0<br>02.01.002 |
| <b>GENERAL</b>    | Updated AT command <b>AT+CGSN</b> to support querying IMEI number and SN number.   | R07A08_01.0<br>02.01.002 |
| <b>GENERAL</b>    | Solved the problem of incorrect default value of <b>ATX</b> queried by <b>AT&amp;V</b> .   | R07A08_01.0<br>02.01.002 |
| <b>GENERAL</b>    | Solved the problem that the IPV6 domain name address resolved by <b>AT+QIDNSGIP</b> was incorrect.   | R07A08_01.0<br>02.01.002 |
| <b>GENERAL</b>    | Update KDDI MBN version to 202004041.  | R07A08_01.0<br>02.01.002 |
| <b>GENERAL</b>    | Updated the SBM MBN version to 202004211.  | R07A08_01.0<br>02.01.002 |
| <b>FILE</b>       | Solved the problem that data may lost when upload files by sending FILE related commands on UART/debug ports.  | R07A08_01.0<br>02.01.002 |



|         |   |                          |
|---------|---|--------------------------|
| GENERAL | Changed the number of attachment returned by <b>AT+QCFG="siminvalirecovery"</b> from 208 to (0-1).  | R07A08_01.0<br>02.01.002 |
| GENERAL | Changed the range value returned by <b>AT+QDAI=?</b> from (1-4) to (1-6).   | R07A08_01.0<br>02.01.002 |
| GENERAL | Solved the problem of an error returned when setting SGMI by <b>AT+QSGMIICFG="config"</b> .   | R07A08_01.0<br>02.01.002 |
| GENERAL | Updated Verizon MBN version to 202004091.   | R07A08_01.0<br>02.01.002 |
| MQTT    | Fixed module RI changed but no URC reported when sending data via MQTT protocol.  | R07A08_01.0<br>02.01.002 |
| GENERAL | Updated TF_Germany_VoLTE to support VoLTE.  | R07A08_01.0<br>02.01.002 |
| GENERAL | Solved the problem that after setting the band to a fixed value, the band value would resume to the default value after the module rebooted twice or three times. | R07A08_01.0<br>02.01.002 |
| GENERAL | Registered to the network with APN1 for CMCC.   | R07A08_01.0<br>02.01.002 |
| GENERAL | Optimized the <b>AT+QCFG="airplanecontrol"</b> command to support setting QMI not to exit the flight mode when pulling w_disable to low.                          | R07A08_01.0<br>02.01.002 |
| GENERAL | Solved the problem that the local time queried by <b>AT+CCLK</b> was inconsistent with the local time synchronized by <b>AT+CTZU=3</b> from the network.          | R07A08_01.0<br>02.01.002 |
| GENERAL | Solved the problem of USB disconnection.  | R07A08_01.0<br>02.01.002 |
| DFOTA   | Solved the problem of 502 and 520 error codes reported after rebooting the module due to powering down when DFOTA upgrade to 90%.                                 | R07A08_01.0<br>02.01.002 |
| GENERAL | Optimized AT command <b>AT+QCFG="ppp/sleep_ri"</b> to solve the problem of no sleep_ri jitter after receiving PPP data.   | R07A08_01.0<br>02.01.002 |
| NETWORK | Optimized China Telecom B5 to search frequency 2452 in priority.  | R07A08_01.0<br>02.01.002 |
| FILE    | Optimized SFS data resume upload function.  | R07A08_01.0<br>02.01.002 |
| NETWORK | Optimized AT command <b>AT+QNETINFO</b> .   | R07A08_01.0<br>01.01.001 |
| NETWORK | Optimized IMEI backup protection mechanism.   | R07A08_01.0<br>01.01.001 |
| DFOTA   | Improved the feature of DFOTA.  | R07A08_01.0<br>01.01.001 |
| HTTP    | Changed the number of the parameter <index> of AT command <b>AT+QHTTPCFGEX</b> to be 40 from 12.  | R07A08_01.0<br>01.01.001 |
| NETWORK | Improved the module stability when failed to encode with ANS1.  | R07A08_01.0<br>01.01.001 |
| AUDIO   | Solved the problem that two sessions would be opened during a call.   | R07A08_01.0<br>01.01.001 |

|         |  |                          |
|---------|--|--------------------------|
| NETWORK | Optimized AT command <b>AT+QCOPS</b> to search nearby PLMN information as many as possible.  | R07A08_01.0<br>01.01.001 |
| HTTP    | Updated the encode_buffer size from 1024 to 2048 bytes for supporting long URL.  | R07A08_01.0<br>01.01.001 |
| ECM     | Solved the problem that the ECM could not be mounted in Linux kernel with later version.   | R07A08_01.0<br>01.01.001 |
| AUDIO   | Optimized AT command <b>AT+QLTONE</b> .  | R07A08_01.0<br>01.01.001 |
| WIFI    | Solved the problem that TCP SERVER could not be established after executing <b>AT+QWTOCLIEN=1</b> .  | R07A08_01.0<br>01.01.001 |
| GENERAL | Solved the problem that the positioning mode always be 2D after positioning.   | R07A08_01.0<br>01.01.001 |
| GENERAL | Changed the default value of appid for Verizon of AT command <b>AT+QGPSCFG="appidname"</b> .   | R07A08_01.0<br>01.01.001 |
| AUDIO   | Solved the problem that the AT performance port would not work after executing <b>AT+QRXIIR?</b> .   | R07A08_01.0<br>01.01.001 |
| NETWORK | Updated Verizon MBN.   | R07A08_01.0<br>01.01.001 |
| DTMF    | Optimized the feature of DTMF.   | R07A08_01.0<br>01.01.001 |
| FTP     | Improved FTP feature under IPv6.   | R07A08_01.0<br>01.01.001 |
| HTTP    | Improved HTTP feature under IPv6.  | R07A08_01.0<br>01.01.001 |
| AUDIO   | Solved the problem that UAC has no sound during a call.  | R07A08_01.0<br>01.01.001 |
| GENERAL | Solved the problem of USB disconnection.   | R07A08_01.0<br>01.01.001 |
| TCP SSL | Optimized the reuse logic of SSL session.  | R07A08_01.0<br>01.01.001 |
| HTTP    | Solved the problem that the file pointer could not be closed normally when sending files with <b>AT+QHHTTPSEND</b> .                         | R07A08_01.0<br>01.01.001 |
| MQTT    | Optimized the feature of MQTT.   | R07A08_01.0<br>01.01.001 |
| TCP SSL | Optimized the feature of SSL.  | R07A08_01.0<br>01.01.001 |
| GENERAL | Solved the problem that the first sentence of command <b>AT+QGPSTIME="GSV"</b> would be messed if the number of GSV sentence is more than 4. | R07A08_01.0<br>01.01.001 |
| GENERAL | Updated TELUS MBN to 0x05800C43.   | R07A08_01.0<br>01.01.001 |
| GENERAL | Updated VoLTE-ATT MBN to version 0x0501033C.   | R07A07_01.0<br>02.01.002 |
| NETWORK | Solved the problem that when executing <b>AT+QCFG="nwscanmode"</b> to fix 2G network in the case of auto                                     | R07A07_01.0              |

|         |  |                          |
|---------|--|--------------------------|
|         | registering network, no CREG reporting and no cell information of CGREG reporting after setting <b>AT+CREG=2</b> , <b>AT+CGREG=2</b> and <b>AT+CREG=2</b> .            | 02.01.002                |
| NETWORK | Solved the problem that there was no LTE result when executing <b>AT+QCOPS=7,0</b> and <b>AT+QCOPS=4,0</b> .   | R07A07_01.0<br>02.01.002 |
| DFOTA   | Solved the problem that the module would reboot and restore repeatedly after DFOTA upgrade.  | R07A07_01.0<br>02.01.002 |
| NETWORK | Changed the roaming state to home service when 313-100 SIM was registered on a 310-410 PLMN.   | R07A07_01.0<br>02.01.002 |
| GENERAL | Removed the function of APN Disable/Enable.  | R07A07_01.0<br>02.01.002 |
| GENERAL | Updated the default address of dmacc to 4g2.vzw.com.   | R07A07_01.0<br>02.01.002 |
| AUDIO   | Solved the problem of low WB downlink volume.  | R07A07_01.0<br>02.01.002 |
| AUDIO   | Solved the problem that DTMF playing without sound when answering a call.  | R07A07_01.0<br>02.01.002 |
| AUDIO   | Solved the problem that voice over USB feature was not available.  | R07A07_01.0<br>02.01.002 |
| DFOTA   | Solved the problem that the error code <b>DELTA_UPDATE_CHECK_FILE_FAILED</b> and <b>IP_PREVIOUS_UPDATE_FAILED</b> of US VERIZON were not reported after DFOTA upgrade. | R07A07_01.0<br>02.01.002 |
| MMS     | Solved the small probability problem that MMS could not be received.   | R07A07_01.0<br>02.01.002 |
| GENERAL | Improved the capability of FGI bit20.  | R07A07_01.0<br>02.01.002 |
| GENERAL | Solved the problem that client could not connect to network after executing <b>AT+QWWAN=1</b> .  | R07A07_01.0<br>02.01.002 |
| DFOTA   | Optimized DFOTA upgrade.   | R07A07_01.0<br>02.01.002 |
| TCP SSL | Extended the command <b>AT+QSSLCFG="cacertex"</b> to add multiple CA certificates.   | R07A07_01.0<br>02.01.002 |
| GENERAL | Solved the problem that the partition of usrdata and data would be formatted unexpectedly.   | R07A07_01.0<br>02.01.002 |
| MQTT    | Corrected the MSG_ID that reported when MQTT sending message timeout.  | R07A07_01.0<br>02.01.002 |
| DFOTA   | Solved the DFOTA upgrade failure.  | R07A07_01.0<br>02.01.002 |
| QMI     | Solved the problem that error occurred after executing command <b>AT\$QCRM_CALL</b> .  | R07A07_01.0<br>02.01.002 |
| NETWORK | Changed the maximum band number to be searched by command <b>AT+QCOPS</b> .  | R07A07_01.0<br>02.01.002 |
| TCP/UDP | Supported to report DATA LENGTH within TCPIP URC reported under the buffer mode.   | R07A07_01.0<br>02.01.002 |

|         |   |                          |
|---------|---|--------------------------|
| GENERAL | Optimized GPS performance.  | R07A07_01.0<br>02.01.002 |
| GENERAL | 1. Controlled SAR on and off through GPIO pins.<br>2. Optimized <b>AT+QCFG="sarcfg"</b> to configure SAR power maximum and falling gradient for specific band of LTE/WCDMA.   | R07A07_01.0<br>02.01.002 |
| FILE    | Optimized FILE related commands to support one more file type.  | R07A07_01.0<br>02.01.002 |
| DFOTA   | Solved the problem that there was SDCARDSTART and SDCARDEND URC reported unexpectedly when executing <b>AT+QFOTADL</b> .  | R07A07_01.0<br>02.01.002 |
| FTP     | Solved the problem that an error would be reported unexpectedly when the FTP transmission was not continuous.   | R07A07_01.0<br>02.01.002 |
| GENERAL | Solved the probability problem that modules rebooting failed when the modem loaded MBN.   | R07A07_01.0<br>02.01.002 |
| GENERAL | Solved the problem that subcommands <b>AT+QSSLCFG="dtls"</b> and <b>AT+QSSLCFG="dtlsversion"</b> was lacked when executing <b>AT+QSSLCFG=?</b> .  | R07A07_01.0<br>02.01.002 |
| WIFI    | Solved the problem that WIFI configuration lost after modules rebooted.   | R07A07_01.0<br>02.01.002 |
| GENERAL | Solved the problem that AT command <b>AT+QFWDCLIENT</b> could not link to Qserver successfully.   | R07A07_01.0<br>02.01.002 |
| DFOTA   | Fixed the problem of URC message return error during DFOTA upgrade.   | R07A07_01.0<br>02.01.002 |
| GENERAL | Disabled the module to retry SIM card detecting after the UICC card was mismatched.   | R07A07_01.0<br>02.01.002 |
| DFOTA   | Opened the serial port for URC output at the baud rate that the customer set during the recovery process.   | R07A07_01.0<br>02.01.002 |
| FTP     | Solved the problem of serial port abnormality while returned ERROR directly after returning CONNECT via commands <b>AT+QFTPPUT</b> , <b>AT+QFTPGET</b> , <b>AT+QFTPLIST</b> and <b>AT+QFTPNLST</b> under PORT mode. | R07A07_01.0<br>02.01.002 |
| HTTP    | Solved the problem of returning +CME ERROR: 702 when executing AT commands <b>AT+QHTTPPOST</b> and <b>AT+QHTTPPUT</b> .   | R07A07_01.0<br>02.01.002 |
| GENERAL | Optimized the file system backup restore mechanism.   | R07A07_01.0<br>02.01.002 |
| NETWORK | Supported WCDMA BAND19 for AT command <b>AT+QCFG="BAND"</b> .   | R07A07_01.0<br>01.01.001 |
| GENERAL | Optimized parameter partition restore mechanism.  | R07A07_01.0<br>01.01.001 |
| GENERAL | Solved the problem that no response returned or URC for manufacturer when executing <b>AT+CMEE=0</b> .  | R07A07_01.0<br>01.01.001 |
| NTP     | Solved the problem of format error when executing AT command <b>AT+QCFG="NTP"</b> .   | R07A07_01.0<br>01.01.001 |
| GENERAL | Solved the problem of returned format error when executing AT command <b>AT+CCLK?</b> .   | R07A07_01.0<br>01.01.001 |
| GENERAL | Solved the problem that when set the parameter of <b>AT+CTZU</b> to illegal value 2, it would be set and take effect unexpectedly, not fail.  | R07A07_01.0              |

|                |  |                          |
|----------------|--|--------------------------|
|                |  | 01.01.001                |
| <b>GENERAL</b> | Set that when the SIM card was locked in PUK2, allowed to execute <b>AT+CPIN=&lt;PUK2&gt;,&lt;new PIN2&gt;</b> to unlock PUK2. | R07A07_01.0<br>01.01.001 |
| <b>TCP/UDP</b> | Supported to report the data length also when TCPIP reporting URC.   | R07A07_01.0<br>01.01.001 |
| <b>GENERAL</b> | Solved the problem that thermal engine isn't working.  | R07A07_01.0<br>01.01.001 |
| <b>GENERAL</b> | Updated the TS25 PLMN list.  | R07A07_01.0<br>01.01.001 |
| <b>AUDIO</b>   | Solved the problem of no sound on pcm slave mode.  | R07A07_01.0<br>01.01.001 |
| <b>AUDIO</b>   | Supported pcm slot to be configurable.   | R07A07_01.0<br>01.01.001 |
| <b>TCP/UDP</b> | Solved the problem that if TCP half-closed, error returned when executing <b>AT+QISEND=0,0</b> .                               | R07A07_01.0<br>01.01.001 |
| <b>GENERAL</b> | Optimized single image upgrade.  | R07A07_01.0<br>01.01.001 |
| <b>DFOTA</b>   | Solved the DFOTA upgrade failure.  | R07A07_01.0<br>01.01.001 |
| <b>MQTT</b>    | Solved the problem that the module could not receive more than 1024 bytes of data sent by the MQTT server.                     | R07A07_01.0<br>01.01.001 |
| <b>PPP</b>     | Solved the problem that the host could not establish PPP under the GSM network.  | R07A06_01.0<br>01.01.001 |
| <b>AUDIO</b>   | Fixed the problem that the incoming call has no ringtone.  | R07A06_01.0<br>01.01.001 |
| <b>TCP/UDP</b> | Solved the problem that when established multiple TCP connection, it was abnormally to loop QIRD quickly.                      | R07A05_01.0<br>01.01.001 |
| <b>NETWORK</b> | Added cell blacklist function when RRC access failure reached a certain condition.   | R07A05_01.0<br>01.01.001 |
| <b>GENERAL</b> | Optimized file system protection mechanism.  | R07A05_01.0<br>01.01.001 |
| <b>NETWORK</b> | Solved the issue that scanning flag was not cleared when executing <b>AT+QCOPS</b> returned error.                             | R07A04_01.0<br>01.01.001 |
| <b>DFOTA</b>   | Optimized DFOTA process.   | R07A04_01.0<br>01.01.001 |
| <b>AUDIO</b>   | Optimized below AT commands<br><b>AT+QAUDCFG="alc5616/dlgain",</b><br><b>AT+QAUDCFG="alc5616/ulgain".</b>                      | R07A04_01.0<br>01.01.001 |
| <b>TCP SSL</b> | Modified SSL to support<br>TLS_ECDHE_RSA_WITH_AES_256_GCM_SHA384.  | R07A04_01.0<br>01.01.001 |

## 5. Known Issues

| Item/Category | Brief Description |
|---------------|-------------------|
| /             | /                 |

Quectel  
confidential

## 6. Functions

| Basic Function    |            |                                |          |       |                  |           |                    |                    |
|-------------------|------------|--------------------------------|----------|-------|------------------|-----------|--------------------|--------------------|
| SMS               | Voice Call | Data Call                      | Fax      | USSD  | PHB              | STK       | CMUX               | FILE <sup>1)</sup> |
| Y                 | Y          | N                              | N        | N     | Y                | N         | Y                  | Y                  |
| Protocol Function |            |                                |          |       |                  |           |                    |                    |
| QMI               | TCP/UDP    | PPP                            | FTP      | HTTP  | NITZ             | NTP       | TCP SSL            | MMS <sup>2)</sup>  |
| Y                 | Y          | Y                              | Y        | Y     | Y                | Y         | Y                  | Y                  |
| SMTP              | PING       | SMTPS                          | HTTPS    | MQTT  |                  |           |                    |                    |
| Y                 | Y          | Y                              | Y        | Y     |                  |           |                    |                    |
| Special Function  |            |                                |          |       |                  |           |                    |                    |
| SIM Detection     | DFOTA      | Quec Locator 2.0 <sup>3)</sup> | ECM      | MBIM  | Dual UART        | TTS       | DTMF <sup>4)</sup> | UAC                |
| Y                 | Y          | Y                              | Y        | Y     | Y                | Y         | Y                  | Y                  |
| RNDIS             | WIFI       | SD                             | LowPower | RMNET | BT <sup>5)</sup> | QuecThing |                    |                    |
| Y                 | Y          | Y                              | Y        | Y     | Y                | Y         |                    |                    |

### NOTES

- Y means the firmware supports this function.
- N means the firmware does not support this function.
- <sup>1)</sup> Supports RAM FILE only.
- <sup>2)</sup> Supports MMS sending only.
- <sup>3)</sup> QuecLocator 2.0 is an efficient location technology developed by Quectel, While it's not free, you need pay for it if you would like to use it.
- <sup>4)</sup> Supports DTMF decoding only.
- <sup>5)</sup> Supports BLE, SPP and HFG.
- Verification Environment is shown below. For more details, please contact Quectel technical support.  
For Windows,  
USB Driver: Quectel\_LTE\_Windows\_USB\_Driver\_V2.2.4  
Qflash Tool: QFlash\_V5.5  
  
For Linux,



QFirehose Tool: Quectel\_LTE&5G\_QFirehose\_Linux&Android\_V1.4.8

USB Driver: Quectel\_LTE&5G\_Linux\_USB\_Driver\_V1.0

QMI\_WWAN Driver: Quectel\_Linux&Android\_QMI\_WWAN\_Driver\_V1.2.1

GobiNet Driver: Quectel\_Linux&Android\_GobiNet\_Driver\_V1.6.3

Quectel-CM Tool: Quectel\_QConnectManager\_Linux\_V1.6.1

QLog Tool: Quectel\_QLog\_Linux&Android\_V1.5.8

Quectel  
confidential